

MTS330i(-R)**3-Stage Fan Coil Thermostat**

Dear Customer:

Thank you for choosing a quality product from Marsus Com Company. Before using this digital thermostat please do study this guide carefully

1) Specifications:**• Supply:**

Voltage..... $220 \pm 20\%$ Vac
Frequency.....50/60 Hz

• Load:

Voltage.....220 Vac
Max Current (MTS330i).....1.5 A
Max Current (MTS330i-R).....6 A

• Features:

Setting Temperature.....10~35 °C
Measuring Temperature.....0~50 °C
Accuracy ± 1 °C
Display Resolution.....0.5 °C
Control Hysteresis.....1 °C

• Physical Specifications

Dimensions.....125x96x40mm
Weight.....175gr
IP.....20
Storage Temp.....-10~70 °C
Maximum Humidity.....85% RH

2) Installation & Wiring:

Caution! This thermostat should be installed by an electrician according to figures A-D.

Connect Phase (PH) and Null (N) to the main power.

Thermostat outputs (L, M and H) should be connected to fan coil motor according to Figure 2.


3) Setting:

In order to turn on/off the thermostat, hold down On-Off key (I) for 3 second.


According to Figure 1, click the Mode key (II) to change mode from heating to cooling and vice versa.

The icons ☀/❄ will be turned on in heating/cooling mode. Also change fan speed among 1, 2, 3 and Auto by clicking the Fan Key (I) and see the result on the left side of the display. Set the desired temperature between 10 to 35 °C by turning the setting volume (III). While setting the set point temperature, you can see its value on the display. It will return to idle state if no change made during 3 seconds.

Thermostat keys will be locked by holding down the keys I & II for 1 second.

Figure 1**شکل (۱)**

- (I) کلید فن / روشن - خاموش
- (II) کلید سرمایش / گرمایش
- (III) ولوم تنظیم دما
- Lock Key.....(I+II)

Figure 2**شکل (۲)****(۱) مشخصات:****• تغذیه :**

$220 \pm 20\%$ Vac.....ولتاژ
 $50/60$ Hz.....فرکانس

• بار خروجی :

220 Vac.....ولتاژ
1/5 A(MTS330i) حداکثر جریان
6 A(MTS330i-R) حداکثر جریان

• قابلیت ها :

$10 \sim 35$ °C.....محدوده تنظیم دما
 -50 °C.....محدوده اندازه گیری دما
 ± 1 °C.....دقت اندازه گیری
 0.5 °C.....دقت نمایش
 1 °C.....حساسیت کنترل

• مشخصات فیزیکی :

125x96x40 mm.....ابعاد
175 gr.....وزن
20درجه حفاظت (IP)
-10~70 °C.....دماهی تکه داری
85 %RH.....حداکثر رطوبت محیط

(۲) نصب و سیم بندی:

هشدار! نصب این ترمومتر باید توسعه تکنسین بر قریب و مطابق اشکال صفحه بعد تا (A) انجام گیرد.

سیم های فاز (PH) و نول (N) می بایست به برق شیر و ترمینال های L، M و H مطابق شکل ۲ به موتور فن کویل متصل گردد.

(۳) تنظیم:

برای روشن / خاموش نمودن ترمومتر، کلید I را به مدت ۳ ثانیه فشار دهید.


با توجه به شکل (۱)، توسط کلید عملکرد (III)، حالت سرمایشی یا گرمایشی را انتخاب نمایید. در حالت گرمایشی، علامت ☀ و در حالت سرمایشی، علامت ❄ روی نمایشگر نمایش داده می شود. همچنین با فشردن متنابو کلید I دور فن بین دور ۱، ۲، ۳ و اتوماتیک تغییر وضعیت داده و تنظیمات در سمت چپ نمایشگر، نشان داده خواهد شد.

می توانید با چرخش ولوم تنظیم دما (کلید III)، دمای مطلوب را بین ۱۰ تا ۳۵ درجه سانتیگراد تنظیم نمایید. در هنگام کار با ولوم تنظیم دما، نمایشگر دمای نقطه تنظیم را روی نمایشگر نشان داده و در صورت عدم ایجاد تغییر به مدت ۳ ثانیه، به حالت عادی (نمایش دمای محیط) باز می گردد.


فشردن همزمان کلیدهای I و II به مدت ۱ ثانیه موجب قفل شدن کلیدهای ترمومتر می گردد.

۴) نحوه نصب ترموموستات:


A



B



C



D

